## **BUILDING SAFETY CERTIFICATE**

No.

Date: 26-04-29

Certified that the existing building Oxford International School (name of the building or premises) Village Jian at Hoshiarpur (address) Is having block (s)/floors as per below:-

Detail of Block (s) in School	Block (1)	Block (2)	Block (3)	Block(4)	Block (5)	Block (6)
No of Floor (s) in the Block	Ground floor, First floor, Second floor	NA	NA	NA	NA	NA

This building is owned/occupied by Oxford International School (name of the Institution) are inspected by the officer's concerned of Sub Divisional Engineer, Provincial Sub Division No. 2 PWD B&R Hoshiarpur (Name of Department/Govt) on 01.04.2024 (date of inspection) in the presence of Mrs. Navjot Kaur, Principal, Oxford International School, Hoshiarpur (name and addresses of the Manager/Secretary or his representative) and that the building/premises is found safe & fit for occupancy upto classes XII (X/XII) with effect from 19.04.2024 for a period of one year in accordance with rule and subject to compliance of specific conditions as appended:-

1. There should not be gathered water on the roofs and surrounding the building.

If there is found any type of crack in any part of the building then the said spot should be vacated immediately and immediately should be done.

3. If you want to make additional construction except to the site plan attached then approval should be granted from the department.

4. This certificate is valid for the period of one year after issuance of this letter.

Issued on 19.04.2024 at Hoshiarpur by Executive Engineer, Provincial Division Hoshiarpur.

\*Strike out whichever is not applicable

Signature and Seal...

Name- Rajiv Kumar Saini

Designation: Executive Engineer

Name & Address of Department/Office: Provincial Division, PWD, B&R, Hoshiarpur

Note: This certificate should be signed/ issued by Assistant Engineer & above officer of concerned Govt. Department only

\*The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploading along with the original vernacular certificate as a single pdf.

> Oxford International School Hsp.-Chd. Road, Hoshiarpur

ਕ ਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਤੋਂ ਤੇ ਮ ਸਾਖਾ ਹੁਸ਼ਿਆਰਪੁਰੇ।

हेंल

	The Principal in a school
	the Poincipal school school solventional school solvention Hosniant
-,	
	京田田 29/ 「HST /9-04- 24 2 024、2
हिम्गं :-	ਇਸੂ ਆਫ ਬਿਲਡਿੰਗ ਸੈਫਟੀ ਸਰਟੀਫਿਕੇਟ ਫਾਰ ਦੀ ਯੀਅਰ
ਹਵਾਲਾ :-	ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰਮਿਤੀ
	ਉਪਰੋਕਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਨਿੰਗੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰਰਾਤਿੰਟ ਉਪ
ਮੰਡਲ ਨੰ:	- ਗੁਜ਼ਿਆਗਰ ਵਲੋਂ ਕੀਤਾ ਜ਼ਿਆ ਅਤੇ ਜਿਸ ਜ਼ਿਆ ਤੋਂ
ਅਤੇ ਜਾਲ ===	ਤੇ ਪ੍ਰਾਹੀ ਦੇ ਕਾਰ ਕਾਰ ਕਾਰ ਕਾਰ ਕਿਲਾਤ ਹੋ ਸਿੱਗੇ ਤੋਂ ਹੋਣ ਇਕਰੇ ਆ , ਦਾਇਤਾਂ ਵੱਲ
ਵਿਸ਼ੇਸ ਧਿਆਨ	ਦਿੱਤਾ ਜਾਵੇ : -
i.	ਬਿੱਲਡਿਗ ਦੀਆਂ ਛੱਤਾਂ ਅਤੇ ਆਲੇ ਦੁਆਲੇ ਪਾਣੀ ਨਾ ਖੜਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ।
2.	ਜੇਕਰ ਇਮਾਰਤ ਵਿੱਚ ਕਿਸੇ ਕਿਸਮ ਦੀ ਤਰੇੜ ਵਗੈਰਾ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗਾ ਨੂੰ
ਤੁਰੰਤ ਖਾਲੀ ਕੀ:	ਤਾ ਜਾਵ ਅਤੇ ਉਸ ਦੀ ਰਿਪੇਅਰ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ ।
3.	ਨਾਲ ਨੱਥੀ ਨਕਸ਼ੇ ਤੋਂ ਇਲਾਵਾ ਜੇਕਰ ਆਪ ਵਲੋਂ ਕੋਈ ਵਾਧੂ ਉਸਾਰੀ ਕਰਨੀ ਹੋਵੇ ਤਾਂ ਉਸ
ਦੀ ਮੰਨਜੂਰੀ ਇ	ਸ ਮਹਿਕਮ ਪਾਸੇਂ ਲਈ ਜਾਵੇ।
तेषां ! उवमः	
	ਪ੍ਰਾਤਕ ਮਰਦ ਤੋਂ ਦੇ ਜ਼ਬਦ
ਪਿੱਠ ਔਕਣ ਨੌਂ:	· · · · · · · · · · · · · · · · · · ·
	ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਹੁਸ਼ਿਆਰਪੁਰ ਨੂੰ	ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰਬਰ : ਮਿਤੀ ਉਪ ਮੰਡਲ ਨੇ: ਦੇ ਹਵਾਲੇ ਅਧੀਨ
ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ	।
201 / V	

Secretary
Sant Baba Harnam Singh Ji
Educational Welfare Society

Principal .

Oxford International School
Hsp.-Chd. Road, Hoshiarpur

ਕਾਰਜਕਾਰੀ ਦਿੱਜੀਨੀਅਰ ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ ਹੁਸ਼ਿਆਰਪਰ "